

Application Case Study

Product : Randocut 500
: Fluid type - Emulsion

Customer : Name - Gro. (Rayong , Thailand)
: Products manufactured - Sanitary ware

Application Details : Application on - Faucet
: Operation type - Machining , Drilling
: Material - Brass
: Concentration - Brix 4%
: Water - Tap water
: Oil change interval - 3 month



Issues & Problems

- Coolant used earlier is expensive and no after sales service.
- The oil is easily deteriorate because it is not taken care.
- And also oil filter blockage as well.



Result

1. No more clogging of the filter in the oil tank.
2. After sales service, take care of coolant for better use.
3. Cost down