# Case Studies



### Details:

990ila	Products	Greenex	EC.
980118	Products	Greenex	FC

Applications	Copper & Aluminum Enamel Wire
Customer /Location	TH-H, Chachongsao, Thailand
Previous Lube/Fluids	RO Water
Materials	Copper and Aluminum
Process/Machines	Ultrasonic Cleaning Tank
Customer Requirements	Quality

### Issue/Problems:

• Found oil residue from the wire drawing process.

• The voltage value of the wires is lowered.

### Solutions:

• Concentration: 7%

• Water: RO Water

• Machine: Ultrasonic Cleaning Tank (No Heat)

• Tank Size: 1,500 Liters

• Control Life Time: 2 Months







## Case Studies



### Summary:

### **QC Control**

- The surface of wire is clean and bright.
- Breakdown Voltage Control = 8-9 Kg.V.
- Glycerin breakdown voltage Control = > 3 V.
- Change Solution every 2 month.

#### **Product**

- Enameled Round Aluminum Wire (UEW, AMW-XV)
- Enameled Round Copper Wire (PVF, UEW, PEW, EIW, AIW)



Report By:

Arreephan Seerai

Asst. Sales Manager

24/11/2021