

## Details:

98Oils Products	RANDOCUT 714G
Applications	Machining Part
Customer /Location	BSPP / Rayong , Thailand
Previous Lube/Fluids	Randocut 500
Materials	Steel / Aluminium
Process/Machines	Cutting , Drilling , Turning
Customer Requirements	Reduce the problem of spoilage of coolant

## Issue/Problems :

Previously, customers used coolant is Randocut 500. There is a problem with rotten coolant and smells bad. Because customers use it with groundwater. And the customer's job is get the machine according to the customer's requirements. Material so there are steel, aluminum or even plastic.

## Solutions :

- 1) Test and trial 1 month
- 2) Check :  
Ask for satisfaction from users.  
found that the problem of smell and spoiling better than ever.

## Summary :

After replacing the previous coolant with Randocut-714G. Coolant spoilage slows down. No rotten smell. No rust on both the machine and the workpiece.

